Column Quarantacinque PLUS

Technical data sheet

HAFRO
acqua, per piacere

LEGGENDA
A - Hot water connection 1/2"F *
B - Cold water connection 1/2"F *.
C - Uscita equipotenziale.

X- Equipotential output.
(To be calculated based on height of the user)
* The height above ground for the connection of the hot
and cold water varies with the height from the shower tray.

Operating pressure:
- MIN 150 kPa (1,5 bar)
- MAX 300 kPa (3,0 bar)
Hot water temperature:
- MAX 60°C (140°F)

INSTALLATION:
-Installation must be done on the floor once walls
 are finished and shower tray installed.
-Do not have pipes passing where fixing
 holes have to be made.
-L 'height of the shower head and the shower head
 vary with the height of the positioning of the column
 equipped

CAUTION:
-Provide a protective divider wall so that the
 whirlpool jets do not leak into the room.

MEASURES FOR POSITIONING THE BRACKETS

VISTA
DALL' ALTO

The overall dimensions are given in centimetres.
Actual dimensions can vary by ± 0.5 cm.

Attenzione:
L 'out of' bonding (C) can 'be made either in the right
and the left side of the corner of the wall.

SISTEM	Electrical specificatio			Hydraulic characteristics			Dimension		Overall Dimensions					
									Pack dimension			Weight		
	Volt	VA	Hz	Water consumption	Pressure exercises	Link H/C Water	Width	Height	Lengh	Width	Height	Net	Gros	
	------	-----	-----	lt/min 20	1,5/3,0	1/2"	21	157	164	33	30	8	11	

If the water pressure is higher than indicated, install pressure reducers.
Provide shut-off cocks out of the dimensions of the product for hot and cold water closing.

NOTICE : If the conditions indicated should not be observed, even partially, the safety of the column may be compromised: therefore both the
 guarantee, and the responsibility of the manufacturer for any direct or indirect damage caused by the product are forfeit.
 The lapse of the guarantee, in the hypothesis indicated above, will have as a result the replacement of the parts which are recognized as being
 defective, whithout covering labor costs necessary for the removal of the product.